

VEHICLE INSPECTION REPORT

WJ64BZY

ISUZU D-MAX 2.5TD TURBO

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/09/2014

Year 2014

Mileage 154,528 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN MPATFS86JDT015231

Body Style Pickup Double Cab

MOT Due 31/03/2026

Gearbox MANUAL

Gears 6

Axle Combi 4x4

JUMPS OUT OF GEAR, TAIL GATE LOCKED - NO KEY TOW BAR, ROOF RACK

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Park assist camera
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Badgedecal Front
Missing
Replace



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wing nsf
Dented
Over 30mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Chipped
Multiple Chips



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Cracked
Replace



13: Qtr Panel Moulding os
Missing
Replace



14: Qtr Panel osr
Chipped
Multiple Chips



15: Door osf
Chipped
Multiple Chips



16: Wing osf
Dented
Over 30mm



17: Fuel Flap
Missing
Replace



18: Door Pad osf
Soiled
Heavy



19: Seat Base Cover osf
Soiled
Heavy



20: Steering Wheel
Damaged
Replace



21: Seat Base Cover nsf
Soiled
Heavy

22: Door Pad nsf
Scuffed
Over 25mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK	Poor	Poor	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		