

VEHICLE INSPECTION REPORT

YR69GBU

Ford Transit Connect 220 1.5 ECO BLUE 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 15/10/2019

Year 2019

Mileage 154,686 Miles
Warranted

Fuel Type DIESEL

Colour WHITE

VIN WF0RXXWPGRKJ48952

Body Style Panel Van L1

MOT Due 14/10/2025

CAP Clean £3,125.00

CAP Average £2,750.00

CAP Below £2,175.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH, NEW HEAD GASKET REQUIRED SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Dented
Over 2 Up To 10mm



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Panel Front
Scratched
UpTo 25mm Thru Paint



5: Qtr Panel nsr
Dented
Over 30% Of Panel



6: Qtr Panel osr
Chipped
1 To 5

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK