

VEHICLE INSPECTION REPORT

WX17KFU

Isuzu D-Max 2.5TD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	20/05/2017	VIN	MPATFS86JFT031375	CAP Below	£4,325.00
Year	2017	Body Style	Pickup Double Cab	Gearbox	MANUAL
Mileage	71,092 Miles Warranted	MOT Due	16/04/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£6,725.00	Axle Combi	4x4
Colour	WHITE	CAP Average	£5,700.00		

TOW BAR, ROOF RACK

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel nsr
Cracked
Replace



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Chipped
Multiple Chips



6: Wing osf
Dented
Over 30mm



7: Bumper Front
Scratched
Over 100mm Thru Paint



8: Seat Base Cover nsf
Soiled
Heavy



9: Fascia Panel
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		